

KONG Company Ltd. and KONG Company EU GmbH recalls CL4E Laser Pointer EU

CL4E Laser Pointer EU
 UPC: 0 35585 15500 5
 Lot Numbers: All



Why is this product hazardous?

- Due to the excessive concentration of lead found inside the circuit board at a soldering point.

What to do

- Please immediately stop using and return to point of sale.

Remedies for consumers

- Return to point of sale

Contact

Please reach out to where you purchased for return and reimbursement instructions

Recall questions, email: ProductSafety@KONGcompany.com

Product safety is very important to us and KONG does not knowingly place harmful products on the market. We truly apologize for this inconvenience and appreciate your assistance in this matter.